

针脚排列

- CM37M9x4-100:** DB37公头电缆线转4口DB9 公头针式电缆线
- CM37M25x4-100:** DB37公头电缆线转4口DB25 公头针式电缆线
- CM62M9x8-100:** DB62公头电缆线转8口DB9 公头针式电缆线
- CM62M25x8-100:** DB62公头电缆线转8口DB25 公头针式电缆线



CM37M9 x 4-100









CM37M25 x 4-100



CM62M9 x 8-100



CM62M25 x 8-100



使用螺母接头,即可连接针式设备.

